


**Fabrication Photo Report (EB Arch Segments & Superstructure)
Tampa Steel Erecting Company
December 18, 2013**



Location of Segments Currently Under Fabrication

- Fabrication
- Assembly
- Painting
- Complete



Arch Segments WA8, WA7, WA6, and WA5-S in Laydown Assembly



Arch Segment EA2-S Fit-Up



Arch Segment WA2-N



Arch Segment EA4-S



Arch Segment WA4-N



Arch Segment WA4-S Fit-Up



Arch Segment EA5-N



Arch Segment WA5-N



Arch Segment EA6-N



Arch Segment EA7



Arch Segments waiting to be painted